

November 15, 2017

David Kapturowski
Spruce Environmental
3 Saber Way
Ward Hill, MA 01835-8000 USA
E-Mail: dave@spruce.com

Subject: Spruce/RadonAway Radon Fan Products for Outdoor Use

Dear Mr. Kapturowski

The following Spruce/RadonAway Radon Fan Products have been evaluated and tested by Intertek to the following standard:

UL 507 Issued: 1999/12/13 Ed: 9 Electric Fans

All are suitable for outdoor use. Authorizations to Mark have been issued by Intertek based upon the Listing Reports as of the dates below and continue to remain in effect.

Report No: 93000798 Issue Date: 5/31/1994
GP201, 301, 401, 501

Replaced by Report No. 101835437BOX-001 ***Issue Date 10/27/2014***

Report No: 95002600 Issue Date: 1/17/1996
XR161, XR261, XR161C, XR261C

Replaced by Report No. 101835437BOX-001 ***Issue Date 10/27/2014***

Report No: 95002722 Issue Date: 1/17/1996
XP101, XP151, XP201, XP101C, XP151C, XP201C

Replaced by Report No. 101835437BOX-001 ***Issue Date 10/27/2014***

Report No: 97001766 Issue Date: 1/1/1998
RP385

Replaced by Report No. 101835437BOX-010 ***Issue Date 10/27/2014***

Report No: 98035025 Issue Date: 12/28/1998
RP140, RP145, RP155

Replaced by Report No. 101835437BOX-010 ***Issue Date 10/27/2014***

Report No: J99020914 Issue Date: 8/23/1999
RP260, RP265

Replaced by Report No. 101835437BOX-010 ***Issue Date 10/27/2014***

Report No: J20039143 Issue Date: 2/14/2000
RP140

Replaced by Report No. 101835437BOX-020 ***Issue Date 10/30/2014***

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

If there are any questions regarding the results contained in this report, or any of the other services offered by Intertek, please do not hesitate to contact your dedicated Intertek Project Manager.

Completed by: Peter Sedor

Reviewed by: Kevin Miller

Title: Engineering Team Leader

Title: Chief Engineer

Signature: 

Signature 

Date 11/15/2017

Date: 11/15/2017

Please note: this Letter Report does not represent authorization for the use of any Intertek certification marks.